

FINAL
SUPPLEMENTAL INFORMATION REPORT
WILLAMETTE TEMPERATURE CONTROL
MCKENZIE RIVER SUB-BASIN, OREGON
COUGAR DAM AND RESERVOIR

TABLE OF CONTENTS

	Page
1.0 <u>INTRODUCTION</u>	1
2.0 <u>BACKGROUND</u>	1
2.1 Project Authorization	3
2.2 Construction	3
2.3 Changes Since the Draft SIR	3
3.0 ENVIRONMENTAL COMPLIANCE TO DATE	4
3.1 National Environmental Policy Act Analysis	4
3.2 Clean Water Act Analysis	4
3.2 Biological Assessment/Biological Opinion	4
4.0 DESCRIPTION OF THE ACTION TO DATE	4
4.1 Diversion Tunnel Construction	4
4.2 Tunnel Tap	5
4.3 Drawdown	5
4.4 Intake Tower Construction	5
4.5 Environmental Coordination Committee Meetings	5
4.6 Water Quality and Sediment Monitoring	5
4.6.1 Pre-drawdown water quality	7
4.6.2 Drawdown water quality—turbidity	7
4.6.3 Drawdown water quality—other parameters	10
4.6.4 Summary	11
4.7 Fisheries Monitoring	12
4.8 Spotted Owl Monitoring	13
4.9 BMPs Implemented	13
4.10 Public Information Meeting	14
4.11 Public Review Meeting	14
5.0 PROPOSED MANAGEMENT OPTIONS FOR REMAINING CONSTRUCTION	14
5.1 Discussion and Evaluation of Options	14
5.2 Preferred Option for 2003/2004	16
5.2.1 BMPs for Subsequent Drawdowns	17
5.2.2 BMPs After Drawdown	17
5.2.3 Operation of Blue River Reservoir	17
6.0 DESCRIPTION OF ACTIONS TO BE COMPLETED	17
6.1 2003 Drawdown and Construction	18

6.1.1	Water Quality Monitoring	18
6.1.2	Biological Monitoring	18
6.2	<u>2004 Drawdown and Construction</u>	18
7.0	<u>NEW CIRCUMSTANCES SINCE THE EARLIER NEPA DOCUMENT</u>	18
7.1	<u>Turbidity</u>	18
7.2	<u>Sedimentation</u>	21
7.2.1	Erosion and Sediment Movement within Cougar Reservoir	21
7.2.2	Suspended Sediment Concentrations	21
7.2.3	Sediment Transport Analysis	22
7.3	<u>Sediment Sampling & DDT</u>	23
7.3.1	DDT in Sediment	23
7.3.1.1	June Events	23
7.3.1.2	August Events	23
7.4	<u>Oregon Chub</u>	24
7.5	<u>Analysis of High Turbidity on Spawning Gravel</u>	24
7.6	<u>Analysis of High Turbidity on Aquatic Macroinvertebrates</u>	26
7.7	<u>Analysis of High Turbidity on Fishes</u>	30
7.8	<u>Analysis of Tunnel Tap and Drawdown Events</u>	31
8.0	<u>EFFECTS OF PROJECT ACTIVITIES NOT PREVIOUSLY EVALUATED</u>	33
8.1	<u>Turbidity</u>	33
8.2	<u>DDT in Sediment</u>	35
8.3	<u>Spawning Gravel</u>	35
8.4	<u>Macroinvertebrates</u>	36
8.5	<u>Fisheries</u>	36
8.6	<u>Aquatic Vegetation</u>	36
8.7	<u>Socio/Economic</u>	37
8.8	<u>EWEB</u>	38
9.0	<u>ENVIRONMENTAL EVALUATIONS AND COORDINATION</u>	39
9.1	<u>Evaluation/Mitigation</u>	39
9.2	<u>Significance</u>	40
9.3	<u>Coordination</u>	40
9.4	<u>Review Comments and Responses</u>	41
10.0	<u>FINDINGS AND RECOMMENDATIONS</u>	41
10.1	<u>Findings</u>	41
10.2	<u>Recommendations</u>	42
11.0	<u>REFERENCES</u>	43

TABLES

	Page
Table 1. Water Quality Samples	7
Table 2. Grain Size Characteristics of Sediment	11
Table 3. Cougar SIR Operational Alternative Plans	14
Table 4. Cougar Pool Elevations, 10-90 Percent Non-Exceedance	16
Table 5. Biotic and Habitat Integrity Index Summary	29

FIGURES

Figure 1. Willamette Basin Location Map	2
Figure 2. Discharge and Turbidity at Gage 0.5 Miles Downstream	8
Figure 3. Discharge and Turbidity at Gage Upstream of the Dam	9
Figure 4. Macro-invertebrate Sampling Sites	27
Figure 5. Plot of Biotic and Habitat Integrity Index Scores	28

APPENDICES

Appendix A Water Quality

Appendix B Sediment Quality Evaluation

Appendix C Operational Alternatives – Technical Summary

Appendix D Sediment Concentrations and Discharge Computations

ENVIRONMENTAL ASSESSMENT AMENDMENT